

Work Order ID 147554

Thursday, June 09, 2016 8:53:45 AM

147554

Page 1

Item ID: D350-567-115

Accept

N900040100Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Replacement Interior Window

Start Date: 5/31/2016 Start Qty: 2.00

2

Cust Item ID:

Required Date: 6/8/2016 Req'd Qty: 2.00

2

Customer:

Reference:

Approvals:

Process Plan: ML3Date: **JUN 13 2016**

Tooling:

Date:

Run Start ***NR1***

QC:

Date:

SPC (Y/N):

Date:

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr								
DSI9745-011	A								
IIN-D350-567	E								

100

Document Control

0.00

100

DC

DOCUMENT CONTROL

Memo

0.00

Doc.Control -USB or Paperwork

Photocopy bluefile and create labels per PPP D350-567-115 CHG005

110

Pick Kit

0.00

110

Packaging

Memo

0.00

Packaging

DAS
6
9-89

JUL 13 2016

hmbel Blanc

DAS
21
9-89

16-07-14

2X

DAS
28
9-89

SEP 07 2016

2

JUL 14 2016

DAS
27
9-89DAS
6
9-89

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
12-1 12-2 12-3		12-1 12-2 12-3		Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐		12-1 12-2 12-3	
OTHER : _____					

Work Order ID 147554

Thursday, June 09, 2016 8:53:45 AM

147554

Page 2

Item ID: D350-567-115

Accept

N900040100Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Replacement Interior Window

Start Date: 5/31/2016 Start Qty: 2.00

2

Cust Item ID:

Required Date: 6/8/2016 Req'd Qty: 2.00

2

Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start ***NR1***

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

120

QC4- 100% Inspect kits for completeness

0.00

120

QC

Memo

0.01

Quality Control

2 DAS
28
9-89 SEP 07 2016

130

Packaging

0.00

130

Packaging

Memo

0.00

Packaging

Identify and pack for shipping as per PPP D350-567-115
Location:FG032

PPP
147492

2 DAS
28
9-89 SEP 07 2016

140

QC21- Final Inspection - Work Order Release

0.00

140

QC

Memo

0.03

Quality Control

DAS
21
9-89 SEP 08 2016

DAS
21
9-89 SEP 08 2016

DQA: _____ Date: _____

**WORK ORDER NON-CONFORMANCE / UPDATE**

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS <table style="width:100%; border: none;"> <tr> <td style="border: none;">Skid-tube ☐</td> <td style="border: none;">Cross tube ☐</td> <td style="border: none;">Water Jet ☐</td> <td style="border: none;">Engineering ☐</td> </tr> <tr> <td style="border: none;">Machining ☐</td> <td style="border: none;">Small Fab ☐</td> <td style="border: none;">Prod. Eng. Coord. ☐</td> <td style="border: none;">Quality ☐</td> </tr> <tr> <td style="border: none;">Thermoforming ☐</td> <td style="border: none;">Finishing ☐</td> <td style="border: none;">Rec/Store/Packaging ☐</td> <td style="border: none;">Other ☐</td> </tr> <tr> <td style="border: none;">Large Fab ☐</td> <td style="border: none;">Composite ☐</td> <td style="border: none;">Supplier ☐</td> <td></td> </tr> </table>						Skid-tube ☐	Cross tube ☐	Water Jet ☐	Engineering ☐	Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐	Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐	Large Fab ☐	Composite ☐	Supplier ☐	
Skid-tube ☐	Cross tube ☐	Water Jet ☐	Engineering ☐																						
Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐																						
Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐																						
Large Fab ☐	Composite ☐	Supplier ☐																							
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval																		
Description Work Order Deviation				Disposition				Completed By																	
								Lead hand / Supervisor Approval Verification																	
								QC / QA Coordinator Approval																	
Root Cause		FAULT CATEGORY																							
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐	OTHER : _____																			

Thursday, June 09, 2016 8:53:48 AM

147554

D350-567-115

Start Date: 5/31/2016**Required Date:** 6/8/2016

Start Qty: 2.00

Required Qty: 2.00

Comments: IPP Rev:A New Issue 04-08-24 JLM
IPP Rev:B CHG#2 ECN 1055 07-11-21 DD verified by:EC
IPP Rev:C 08-10-07 as per revD DD verified by: IPP REV:D
13.10.15 AS PER IIN REV.E DD VERF:JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
AN3-4A *AN3-4A* Bolt		Purchased	No			110	Each	72.0000	4	8			
				<u>Location</u>				<u>Loc Qty</u>		<u>Loc Code</u>			
				ST350				72					
					m134502			72					
AN526C632R12 *AN526C632R12* Screw		Purchased	No			110	Each	159.0000	9	18			
				<u>Location</u>				<u>Loc Qty</u>		<u>Loc Code</u>			
				ST327				159					
					m134180			159					
D2463 *D2463* 1/2" Seal (\$Per Foot)		Manufactured	No			110	f	405.0295	4.41	8.82			
				<u>Location</u>				<u>Loc Qty</u>		<u>Loc Code</u>			
				ST409				405.0294737					
					140013			405.029474					
D3293-1 *D3293-1* Doubler For Interior Window For -111		Manufactured	No			110	Each	5.0000	1	2			
				<u>Location</u>				<u>Loc Qty</u>		<u>Loc Code</u>			
				ST434				5					
					141576			5					

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐
OTHER : _____					

Picklist Print

Thursday, June 09, 2016 8:53:48 AM

Page 2

Work Order ID: 147554

147554

Parent Item: D350-567-115

D350-567-115

Parent Item Name: Replacement Interior Window

Start Date: 5/31/2016

Required Date: 6/8/2016

Start Qty: 2.00

Required Qty: 2.00

D3294-1

Manufactured No

110

Each

6.0000

1 2

D3294-1

Bracket For Interior Window For -115

**

DAS
6
9-89
DAS
27
9-89

Location

Loc Qty

Loc Code

ST435

6

142831

6

2

D3295-041

Manufactured No

110

Each

5.0000

1 2

D3295-041

Replacment Interior Window For -111

**

DAS
6
9-89
DAS
27
9-89

Location

Loc Qty

Loc Code

ST436

5

142871

1

145944

4

2

D3296-041

Manufactured No

110

Each

0.0000

1 2

D3296-041

Replacement Interior Door For -111

**

DAS
6
9-89
DAS
27
9-89

D5420-1

Manufactured No

110

Each

15.0000

1 2

D5420-1

Doubler Plate

**

DAS
6
9-89
DAS
27
9-89

Location

Loc Qty

Loc Code

prelim

1

144528

1

ST164

14

145036

14

2

DT8439

Manufactured No

110

Each

0.0000

1 2

DT8439

TEMPLATE

**

DAS
6
9-89
DAS
27
9-89

JUL 14 2016

DQA: _____ Date: _____

**WORK ORDER NON-CONFORMANCE / UPDATE**

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐
OTHER : _____					

Picklist Print

Thursday, June 09, 2016 8:53:48 AM

Page 3

Work Order ID: 147554

147554

Parent Item: D350-567-115

D350-567-115

Parent Item Name: Replacement Interior Window

Start Date: 5/31/2016

Required Date: 6/8/2016

Start Qty: 2.00

Required Qty: 2.00

MS20426AD3-5

Purchased

No

110

Each

4,519.000

8

16

MS20426AD3-5

Rivet

DAS
28
9-89

Location

Loc Qty

Loc Code

GA

4120

4533

4120

ST312

399

4444

399

MS20470AD4-5

Purchased

No

110

Each

2,474.000

2

4

MS20470AD4-5

RIVET, UNIVERSAL HEAD

DAS
28
9-89

Location

Loc Qty

Loc Code

GA

780

m133860

780

ST310

1694

m134654

1694

MS20470AD4-6

Purchased

No

110

Each

3,395.000

115

230

MS20470AD4-6

RIVET

DAS
28
9-89

Location

Loc Qty

Loc Code

CCK004

1566

m134852

1566

GA

509

m131618

85

m133077

424

ST310

1320

m134360

1320

DAS
6
27
9-89
9-89

DAS
6
27
9-89
9-89

DAS
6
27
9-89
9-89

JUL 14 2016

230

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐
OTHER : _____					

Picklist Print

Thursday, June 09, 2016 8:53:48 AM

Page 4

Work Order ID: 147554

147554

Parent Item: D350-567-115

D350-567-115

Parent Item Name: Replacement Interior Window

Start Date: 5/31/2016

Required Date: 6/8/2016

Start Qty: 2.00

Required Qty: 2.00

MS20470AD4-7

Purchased

No

110

Each

3,786.000

15

30

MS20470AD4-7

Rivet, Universal Head

DAS
28
9-89

Location

Loc Qty

Loc Code

CCK004

2792

m134376

1396

m134630

1396

ST310

994

m132536

994

**

DAS
6
9-89
DAS
27
9-89

MS21042L06

Purchased

No

110

Each

159.0000

9

18

MS21042L06

Nut

DAS
28
9-89

Location

Loc Qty

Loc Code

ST303

159

m134474

9

m134537

100

m134962

50

**

DAS
6
9-89
DAS
27
9-89

MS21062L3

Purchased

No

110

Each

26.0000

4

8

MS21062L3

Nut Plate

DAS
28
9-89

Location

Loc Qty

Loc Code

ST300

26

m126275

6

m134781

20

**

DAS
6
9-89
DAS
27
9-89

NAS1149DN632J

Purchased

No

110

Each

648.0000

9

18

NAS1149DN632J

Washer

DAS
28
9-89

Location

Loc Qty

Loc Code

ST264

648

m134370

648

**

DAS
6
9-89
DAS
27
9-89

JUL 14 2016

Thursday, June 09, 2016 8:53:48 AM

Shop Packet Print

Page 4

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐				
Date : _____	Step #: _____	QTY Effective : _____			MRB (QSI042) Approval	
Description Work Order Deviation		Disposition				
					Completed By	
					Lead hand / Supervisor Approval Verification	
					QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐				
OTHER : _____						

DART SERVICE INSTRUCTION

TO AMEND INSTALLATION INSTRUCTIONS D350-567 REV. E
AND INSTRUCTIONS FOR CONTINUED AIRWORTHINESS ICA-D350-567 REV. 2

REF. TCCA STC: SH92-18

REF. FAA STC: SH989NE AND SH990NE

REF. EASA STC: EASA.IM.R.S.01560 AND EASA.IM.R.S.01561

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 143554 MJS
16-06-13

PURPOSE:

To provide a new location for the cabin fire extinguisher for aircraft equipped with P/N 19810-02-00 (SICMA-198 Seat). For further information on SICMA-198 Seats refer to Airbus CMM 25-12-31.

CHANGE:

For aircraft equipped with P/N 19810-02-00 (SICMA-198 Seat) add section 3.2.3, amend section 5.0 Parts List (ICA Section 25.7) and amend section 4.0 Weight and Balance (ICA Section 25.5) of Vertical Reference Window Installation Instructions D350-567 Rev. E (ICA D350-567 Rev. 2) as follows:

- (ADD) 3.2.3 This installation will require access to the under floor structure in the area aft of the pilot's collective stick. To access the under floor structure remove the applicable belly panel in accordance with the applicable Aircraft Maintenance Manual.

Remove and retain the cabin fire extinguisher P/N 1708337 B4 and Fire Extinguisher Support P/N 350A77 0131 40 from existing location. Per Figure 1, select the desired location for the fire extinguisher at either the "Primary" location or "Alternate" location.

Locate the D5420-1 Doubler Plate at the selected location per Figure 1 and transfer mark the holes from the D5420-1 Doubler Plate to the aircraft floor. Drill the nutplate hole pattern shown in Detail A. Touch up the drilled floor surface finish with chemical film (Alodine 1200/1201) per MIL-C-5541 and one coat of MIL-P-85582 or MIL-P-23377 primer.

Locate the D5420-1 Doubler Plate under the floor and install using qty (4) MS21062L3 nutplates and qty (8) MS20426AD3-5 Rivets (rivets fasten through floor and doubler). Locate the Fire Extinguisher Support P/N 350A77 0131 40 over the drilled holes and fasten it to the qty (4) MS21062L3 nutplates using qty (4) AN3-3A Bolts. Torque bolts 20-25 in-lbs (2.3-2.8 N-m). Reinstall the P/N 1708337 Fire Extinguisher per the Aircraft Maintenance Manual.

Reinstall the belly panel per the applicable Aircraft Maintenance Manual.

CHANGE:

Amend Section 25.6 Equipment relocation of ICA D350-567 Rev. 2 as follows:

25.6 EQUIPMENT RELOCATION

- (IS) As part of the D350-567 kit installation, the aircraft data plate may have been relocated beneath the RH pilot's seat and the fire extinguisher may have been relocated to the LH side of the pilot's seat per Eurocopter Service Bulletin 25.00.59. See also Dart Drawing D350-567.

Depending on the Aircraft's seating configuration the fire extinguisher may have to be relocated to the LH side of the pilot's seat per Eurocopter Service Bulletin 25.00.59, or relocated to the cabin floor per Dart DSI 9745. See also Dart Drawing D350-567.

- (WAS) As part of the D350-567 kit installation, the aircraft data plate may have been relocated beneath the RH pilot's seat and the fire extinguisher may have been relocated to the LH side of the pilot's seat per Eurocopter Service Bulletin 25.00.59. See also Dart Drawing D350-567.

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-O-01

APPROVED
BY: *[Signature]*
D. SHEPHERD (DE # 02)
DATE: 16.04.06
CERT. NO.: SH92-18
ISSUE NO.: 6

A	NEW ISSUE (SEE PAR 16-510)	AJS	16.04.06
REV.	DESCRIPTION	BY	DATE
DESIGN	AJS	DART AEROSPACE LTD	
DRAWN	AJS	HAWKESBURY, ONTARIO, CANADA	
CHECKED	<i>[Signature]</i>	DRAWING NO.	REV. A
MFG. APPR.	N/A	DSI 9745	SHEET 1 OF 3
APPROVED	<i>[Signature]</i>	TITLE	SCALE
DE APPR.	<i>[Signature]</i>	ALTERNATE FIRE EX LOCATION	NTS
DATE	16.04.06	COPYRIGHT © 2016 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	

EDIT 5.0/25.7 PARTS LIST:

For customers with kits D350-567-013/-015/-017/-023/-025/-027/-117 @ CHG002 and earlier,
Customers with kits D350-567-111 @ CHG006 and earlier,
Customers with kits D350-567-115 @ CHG004 and earlier,
Customers with kits D350-567-031/-031B/-111B/-115B @ CHG001 and earlier,
Procure kit DSI 9745-011

Item	Qty -011	Part Number	Description
	X	DSI 9745-011	FIRE EXTINGUISHER RELOCATION KIT
1	1	D5420-1	DOUBLER PLATE
2	4	AN3-4A	HEX HEAD BOLT
3	8	MS20426AD3-5	CSK RIVET
4	4	MS21062L3	NUTPLATE

For customers with kits D350-567-013/-015/-017/-023/-025/117 @ CHG003 and later,
Customers with kits D350-567-111 @ CHG007 and later,
Customers with kits D350-567-115 @ CHG005 and later,
Customers with kits D350-567-031/-031B/-111B/-115B @ CHG002 and later,
Refer to Installation Instructions D350-567 and ICA-D350-567 and update the parts list as follows:


EDIT 5.0 ADD:

Qty -013	Qty -023	Qty -113	Qty -115	Qty -031	Part Number	Description
X					D350-567-013	REPLACEMENT WINDOW KIT (SMALL)
	X				D350-567-023	REPLACEMENT WINDOW KIT (LARGE)
		X			D350-567-113	REPLACEMENT WINDOW KIT (EXTRA LARGE)
			X		D350-567-115	INTERIOR FLOOR WINDOW KIT
				X	D350-567-031	INTERIOR FLOOR WINDOW KIT (SLIDING DOOR COMPATABLE)
			1	1	D5420-1	DOUBLER PLATE
			4	4	AN3-4A	HEX HEAD BOLT
			8	8	MS20426AD3-5	CSK RIVET
			4	4	MS21062L3	NUTPLATE

EDIT 4.0/25.5 WEIGHT AND BALANCE:

*Note: Does not include fire extinguisher weight

Installation	Weight	LATERAL		LONGITUDINAL	
		Arm	Moment	Arm	Moment
DSI 9745-011 (Primary Location)	0.1 lb	+1.6 in	+16 in lb	72.2 in	7.2 in lb
Fire Extinguisher Relocation Kit	0.05 kg	+0.04 m	+0.02 m kg	1.83 m	0.1 m kg
DSI 9745-011 (Alternate location)	0.1 lb	-4.4 in	-44 in lb	65.4 in	6.5 in lb
Fire Extinguisher Relocation Kit	0.05 kg	-0.11 m	-0.01 m kg	1.66 m	0.1 m kg

**DETAIL A**

(NUT PLATE HOLE PATTERN)

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-O-01

APPROVED

BY: *[Signature]*
D. SHEPHERD (DE # 02)

DATE: 16.04.06
CERT. NO.: SH92-18
ISSUE NO.: 6

DESIGN	AJS	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA
DRAWN	AJS	
CHECKED	<i>[Signature]</i>	DRAWING NO. REV. A
MFG. APPR.	N/A	DSI 9745 SHEET 2 OF 3
APPROVED	<i>[Signature]</i>	TITLE SCALE
DE APPR.	<i>[Signature]</i>	ALTERNATE FIRE EX LOCATION NTS
DATE	16.04.06	COPYRIGHT © 2016 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.




FIGURE 1

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-O-01

APPROVED
BY: *[Signature]*
D. SHEPHERD (DE # 02)

DATE: 16.04.06
CERT. NO.: SH92-18
ISSUE NO.: 6

DESIGN	AJS	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	AJS		
CHECKED	<i>[Signature]</i>	DRAWING NO.	REV. A
MFG. APPR.	N/A	DSI 9745	SHEET 3 OF 3
APPROVED	<i>[Signature]</i>	TITLE	SCALE
DE APPR.	<i>[Signature]</i>	ALTERNATE FIRE EX LOCATION	NTS
DATE	16.04.06	COPYRIGHT © 2016 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	

Work Order ID 147554

Thursday, June 09, 2016 8:53:45 AM

147554

Page 1

Item ID: D350-567-115 Accept ***N900040100*** Setup Start ***NS1***
 Revision ID: Stop ***NS2***
 Item Name: Replacement Interior Window
 Start Date: 5/31/2016 Start Qty: 2.00 ***2*** Cust Item ID:
 Required Date: 6/8/2016 Req'd Qty: 2.00 ***2*** Customer:

Reference:

Approvals: Process Plan: MCS Date: **JUN 13 2016** Tooling: _____ Date: _____ Run Start ***NR1***
 QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr								
DSI9745-011	A								
IIN-D350-567	E								

100 Document Control 0.00
100 DOCUMENT CONTROL
 DC Memo 0.00
 Doc.Control -USB or Paperwork Photocopy bluefile and create labels per PPP D350-567-115 CHG005

110 Pick Kit 0.00
110
 Packaging Memo 0.00
 Packaging

DAS
21
9-89
JUL 14 2016
2

DAS
28
9.89

5.0 PARTS LIST

Qty -015	Qty -017	Qty -025	Qty -027	Qty -111	Qty -117	Part Number	Description
X						D350-567-015	FLOOR WINDOW INSTALLATION (SMALL)
	X					D350-567-017	FLOOR WINDOW INSTALLATION (SMALL)
		X				D350-567-025	FLOOR WINDOW INSTALLATION (LARGE)
			X			D350-567-027	FLOOR WINDOW INSTALLATION (LARGE)
				X		D350-567-111	FLOOR WINDOW INSTALLATION (EXTRA LARGE)
					X	D350-567-117	FLOOR WINDOW INSTALLATION (EXTRA LARGE)
1	1					D350-567-013	REPLACEMENT WINDOW KIT (SMALL)
		1	1			D350-567-023	REPLACEMENT WINDOW KIT (LARGE)
				1	1	D350-567-113	REPLACEMENT WINDOW KIT (EXTRA LARGE)
	1		1	1		D350-567-115	INTERIOR FLOOR WINDOW KIT
1		1			1	D350-567-031	INTERIOR FLOOR WINDOW KIT (SLIDING DOOR COMPATABLE)

Qty -013	Qty -023	Qty -113	Qty -115	Qty -031	Part Number	Description
X					D350-567-013	REPLACEMENT WINDOW KIT (SMALL)
	X				D350-567-023	REPLACEMENT WINDOW KIT (LARGE)
		X			D350-567-113	REPLACEMENT WINDOW KIT (EXTRA LARGE)
			X		D350-567-115	INTERIOR FLOOR WINDOW KIT
				X	D350-567-031	INTERIOR FLOOR WINDOW KIT (SLIDING DOOR COMPATABLE)
1					D2125	REPLACEMENT WINDOW, SMALL
	1				D2942	REPLACEMENT WINDOW, LARGE
		1			D3290-041	REPLACEMENT WINDOW ASSEMBLY, EXTRA LARGE
1					D2126-0600	SEAL
	1				D2463-0750	NEOPRENE SEAL
		1			D2463-0860	NEOPRENE SEAL
	9	12			2600-6	1/4 TURN FASTENER
	9	12			2600-LW	WASHER
	9	12			212-12	RECEPTACLE
	22	21			AN526C832R9	SCREW (OR AN526C832-9, OR MS51957-126)
	44	42			AN960JD8	WASHER
	22	21			MS21042L08	NUT (OR MS21042-08)
	18	24			MS20426AD3-5	RIVET
2 SQ. YD	2 SQ. YD	2 SQ. YD			N/A	9.7oz 7781 'S' GLASS UNIVERSAL WEAVE
				1	D2463-0450	NEOPRENE SEAL
				1	D3210-1	DOUBLER
				1	D3211-1	BRACKET
				1	D3212-1	FLOOR WINDOW
				1	D3213-041	DOOR ASSEMBLY
			1		D3293-1	DOUBLER
			1		D3294-1	BRACKET
			1		D3295-041	FLOOR WINDOW
			1		D3296-041	DOOR ASSEMBLY
			1		D2463-0530	NEOPRENE SEAL
			9	8	AN526C632R12	SCREW (OR AN526C632-12, OR MS51957-32)
			9	8	AN960JD6	WASHER
			9	8	MS21042L06	NUT (OR MS21042-06)
			2	40	MS20470AD4-5	RIVET
			115	90	MS20470AD4-6	RIVET
			15	20	MS20470AD4-7	RIVET

• COPYRIGHT © 2000 BY DART AEROSPACE LTD. •

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Revision: E

Date: 13.08.15

REFERENCE ONLY

DAS
28

EDIT 5.0/25.7 PARTS LIST:

For customers with kits D350-567-013/-015/-017/-023/-025/-027/-117 @ CHG002 and earlier,
Customers with kits D350-567-111 @ CHG006 and earlier,
Customers with kits D350-567-115 @ CHG004 and earlier,
Customers with kits D350-567-031/-031B/-111B/-115B @ CHG001 and earlier,
Procure kit DSI 9745-011

Item	Qty -011	Part Number	Description
	X	DSI 9745-011	FIRE EXTINGUISHER RELOCATION KIT
1	1	D5420-1	DOUBLER PLATE
2	4	AN3-4A	HEX HEAD BOLT
3	8	MS20426AD3-5	CSK RIVET
4	4	MS21062L3	NUTPLATE

For customers with kits D350-567-013/-015/-017/-023/-025/117 @ CHG003 and later,
Customers with kits D350-567-111 @ CHG007 and later,
Customers with kits D350-567-115 @ CHG005 and later,
Customers with kits D350-567-031/-031B/-111B/-115B @ CHG002 and later,
Refer to Installation Instructions D350-567 and ICA-D350-567 and update the parts list as follows:


EDIT 5.0 ADD:

Qty -013	Qty -023	Qty -113	Qty -115	Qty -031	Part Number	Description
X					D350-567-013	REPLACEMENT WINDOW KIT (SMALL)
	X				D350-567-023	REPLACEMENT WINDOW KIT (LARGE)
		X			D350-567-113	REPLACEMENT WINDOW KIT (EXTRA LARGE)
			X		D350-567-115	INTERIOR FLOOR WINDOW KIT
				X	D350-567-031	INTERIOR FLOOR WINDOW KIT (SLIDING DOOR COMPATABLE)
			1	1	D5420-1	DOUBLER PLATE
			4	4	AN3-4A	HEX HEAD BOLT
			8	8	MS20426AD3-5	CSK RIVET
			4	4	MS21062L3	NUTPLATE

EDIT 4.0/25.5 WEIGHT AND BALANCE:

*Note: Does not include fire extinguisher weight

Installation	Weight	LATERAL		LONGITUDINAL	
		Arm	Moment	Arm	Moment
DSI 9745-011 (Primary Location)	0.1 lb	+1.6 in	+16 in lb	72.2 in	7.2 in lb
Fire Extinguisher Relocation Kit	0.05 kg	+0.04 m	+0.02 m kg	1.83 m	0.1 m kg
DSI 9745-011 (Alternate location)	0.1 lb	-4.4 in	-44 in lb	65.4 in	6.5 in lb
Fire Extinguisher Relocation Kit	0.05 kg	-0.11 m	-0.01 m kg	1.66 m	0.1 m kg



DETAIL A

(NUT PLATE HOLE PATTERN)

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-O-01

APPROVED
BY: *[Signature]*
D. SHEPHERD (DE # 02)

DATE: 16.04.06
CERT. NO.: SH92-18
ISSUE NO.: 6

DESIGN	AJS	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA
DRAWN	AJS	
CHECKED	<i>[Signature]</i>	DRAWING NO. REV. A
MFG. APPR.	N/A	DSI 9745 SHEET 2 OF 3
APPROVED	<i>[Signature]</i>	TITLE SCALE
DE APPR.	<i>[Signature]</i>	ALTERNATE FIRE EX LOCATION NTS
DATE	16.04.06	COPYRIGHT © 2016 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.